MATERIAL SAFETY DATA SHEET

SRM Supplier: National Institute of Standards and Technology

Standard Reference Materials Program

Bldg. 202 RM 211

Gaithersburg, Maryland 20899

SRM Number: 987 MSDS Number: 987

SRM Name: Assay and Isotopic Standard

 $for\ Strontium$

Date of Issue: August 1994 Date of Revision: 1 May 2000

MSDS Coordinator: Joylene W.L. Thomas FAX: (301) 926-4751

Phone: (301) 975-6776 ChemTrec: 1-800-424-9300 E-mail: SRMMSDS@nist.gov

SECTION I. MATERIAL IDENTIFICATION

Material Name: Assay and Isotopic Standard for Strontium

Description: SRM 987 consists of approximately 1 g of highly purified strontium carbonate.

Other Designations: strontium carbonate; carbonic acid, strontium salt; native strontianite

Name Chemical Formula CAS Registry Number

Strontium Carbonate SrCO₃ 1633-05-2

DOT Classification: Not hazardous by DOT regulations

Manufacturer/Supplier: Available from a number of suppliers

SECTION II. HAZARDOUS INGREDIENTS

Hazardous Component	Nominal Concentrations (%)	Exposure Limits and Toxicity Data
Strontium Carbonate	~ 100 %	No TLV-TWA established
		No toxicity data available

SECTION III. PHYSICAL/CHEMICAL CHARACTERISTICS

Strontium Carbonate		
Appearance and Odor: an odorless, tasteless, gray-white granular powder		
Relative Molecular Mass: 147.63		
Density: 3.7		
Melting Point: decomposes at 1100 °C to SrO and CO ₂		
Solubility in Water: soluble in 100 000 parts water; soluble in 1000 parts water saturated with CO ₂		
Solvent in Other Solubility: soluble in dilute acids, ammonium salt solutions, and carbonated water		

MSDS 987 Page 1 of 3

SECTION IV. FIRE AND EXPLOSION HAZA	RD DATA	
Flash Point: N/A	Method Used: N/A	Autoignition Temperature: N/A
Flammability Limits in Air (Volume	%): UPPER: LOWER:	N/A N/A
Extinguishing Media: This material is	s non-flammable. Use extin	nguishing media that is appropriate to the surrounding fire.
Special Fire Procedures: Since the face piece operated in the pressure-dem	* *	es, wear a self-contained breathing apparatus (SCBA) with a full ode.
		ole fire and explosion hazard when exposed to heat and/or flame; it esence of strong oxidizers presents a fire and explosion hazard.
SECTION V. REACTIVITY DATA		
Stability: X Stable	Unstable	
Conditions to Avoid: Avoid oxidizing	g materials.	
Incompatibility (Materials to Avoid)	: See Section IV: Fire an	nd Explosion Hazard Data
Hazardous Decomposition or Byproand strontium.	ducts: Thermal decompose	ition products may include toxic and hazardous oxides of carbon
Hazardous Polymerization:	Will Occur	X Will Not Occur
SECTION VI. HEALTH HAZARD DATA		
Route of Entry: X Inhalation	X Skin	X Ingestion
		conate may cause nasal and respiratory irritation with sneezing and in contact may cause dermatitis and continued eye exposure may
0	in the teeth and bones. So	fects which tend to induce vomiting and diarrhea. With continued ubjected to a chronic diet high in strontium and low in calcium, nation, weakness, and hind leg paralysis.
Signs and Symptoms of Exposure: See	e Section VI: Health Haza	rds (Acute and Chronic)
Medical Conditions Generally Aggrav	ated by Exposure: N/A	
Listed as a Carcinogen/Potential Carc	inogen:	Yes No
In the National Toxicology Program In the International Agency for Rese By the Occupational Safety and Hea	arch on Cancer (IARC) Mo	ens <u>X</u>

MSDS 987 Page 2 of 3

EMERGENCY AND FIRST AID PROCEDURES:

Skin Contact: Remove contaminated shoes and clothing. Rinse affected area with large amounts of water followed by washing the area with soap and water. Obtain medical assistance if necessary.

Eye Contact: Immediately flush eyes, including under the eyelids, with copious amounts of water for at least 15 minutes. Obtain medical assistance.

Inhalation: If inhaled, move the victim to fresh air. If breathing is difficult, give oxygen; if the victim is not breathing, give artificial respiration. Obtain medical assistance if necessary.

Ingestion: If ingested, wash out mouth with water. Obtain medical assistance immediately.

TARGET ORGAN(S) OF ATTACK: skin and the skeletal system

SECTION VII. PRECAUTIONS FOR SAFE HANDLING AND USE

Steps to be Taken in Case Material Is Released or Spilled: Avoid raising dust. Sweep up small spills and place into a clean, dry container for later disposal. Vacuuming or wet sweeping may be used to avoid dust dispersal.

Waste Disposal: Follow all federal, state, and local regulations.

Handling and Storage: Persons handling this material should wear an air-purifying respirator with a high-efficiency particulate filter. The specific respirator selected must be based on contamination levels found in the workplace, must be based on the specific operation, must not exceed the working limits of the respirator, and must be jointly approved by the National Institute for Occupational Safety and Health (NIOSH) and the Mine Safety and Health Administration (MSHA). Additional protective clothing such as gloves, lab coats, and splash-proof or dust-resistant safety goggles should be worn.

NOTE: Contact lenses pose a special problem; soft lenses may absorb irritants and all lenses concentrate them. **DO NOT** wear contact lenses in the laboratory.

Store material in a cool, dry, well ventilated area and protect containers from physical damage.

SECTION VIII. SOURCE DATA/OTHER COMMENTS

Sources: MDL, Information Systems, MSDS Strontium Carbonate, June 2, 1999.

The Merck Index, 11th Ed., 1989.

The Sigma-Aldrich Library of Chemical Safety Date, Ed. II, 1988.

Disclaimer: Physical and chemical data contained in this MSDS are provided only for use in assessing the hazardous nature of the material. The MSDS was prepared carefully, using current references; however, NIST does not certify the data on the MSDS. The certified values for this material are given on the NIST Certificate of Analysis.

MSDS 987 Page 3 of 3